



Customer Notification

July 22, 2026

B-CN-467-EN REV A

SUBJECT: Service Monitoring Tools Release

Purpose

This bulletin announces updates to the Service Monitoring Tools (SMT) for the VT and TT Series Compressors and describes the associated changes.

Summary

VT Series SMT – Version 4.15.0

Applicable Firmware: 1.9 and prior

Changes include:

- Added Locked Rotor Fault status for VFD faults in the Active Warning/Fault Viewer
- Added cavity temperature warning (applicable to FW1.9) under "Motor Cooling Temp Fault" in the Alarms/Fault Viewer
- Added bearing saturation counters to the recording
- Updated the lockup fault log to use fewer indices in place of the "No Faults Recorded" indication

TT Series SMT – Version 3.7.0

Applicable Firmware: 4.5 and prior

Changes include:

- Added Low Suction Pressure Alarm/Fault Delay Timer settings to the Configuration window
- Updated the application branding with the new Danfoss logo
- Added recording enhancements to improve data collection and diagnostics

Application	Current Version Number	Applicable Firmware
VT Series SMT	4.15.0	1.9 and prior
TT Series SMT	3.7.0	4.5 and prior

Action Required

Navigate to our website <https://www.turbocoroem.com/en/categories-page/compressor-software/> to download the latest versions of these software tools. Login credentials are not required for these downloads.

Need Assistance

For more information, please contact your Key Account Manager or our Product Support group at turbocor.ps.na@danfoss.com