



# Customer Notification

September 9, 2026

**B-CN-470-EN REV A**

**SUBJECT: TTS650 and TGS510 Operating Envelope Correction**

---

## Purpose

This bulletin is to inform customers of a labeling error identified in the TTS650 and TGS510 Operating Envelopes contained within the M-AP-001-EN Applications and Installation Manual, Revision U. The Fahrenheit temperature values displayed on the right-hand vertical axis of the operating envelopes (Saturated Discharge Temperature (SDT) [F°]) were not correctly scaled relative to the left-hand axis in Celsius. This labeling error was limited to the High SST envelopes for the TTS650 and TGS510 compressors.

Actual compressor performance and predicted performance are in no way affected. However, compressor operating envelopes may have been misunderstood by customers if reference was taken to the Fahrenheit scale. Customers should reference the corrected values described in this bulletin and available in Revision U.1 of the Applications and Installation Manual, available on our [turbocoroem.com](http://turbocoroem.com) website.

## Summary

The TTS650 and TGS510 operating envelopes published in the M-AP-001-EN Applications and Installation Manual Revision U include incorrect scaling on the right-hand axis (Saturated Discharge Temperature (SDT) [F°]). The operating envelopes can be found on pages 65 and 67 of the manual.

The Celsius temperature scale shown on the graph is correct; however, the corresponding Fahrenheit temperature scale was converted incorrectly.

### Correct Celsius Scale

- 5°C to 70°C


### Incorrect Fahrenheit Scale

- 41°F to 131°F

### Correct Fahrenheit Scale

- 41°F to 158°F

No compressor performance data, operating limits, ratings, or application guidance have changed. The issue is limited to the Fahrenheit axis labeling contained within the graph.




**Figure 1 – Operating Envelope, High SST: TTS650**

Classified as Business

**Danfoss LLC • 1769 E Paul Dirac Drive • Tallahassee, FL 32310 USA • [turbocor.ps.na@danfoss.com](mailto:turbocor.ps.na@danfoss.com) • <http://turbocor.danfoss.com> • Phone +1 850 504 4800**

Danfoss can accept no responsibility for possible errors in catalogues, brochures and other printed material. Danfoss reserves the right to alter its products without notice. This also applies to products already on order provided that such alterations can be made without subsequent changes being necessary in specifications already agreed. All trademarks in this material are property of the respective companies. Danfoss and the Danfoss logotype are trademarks of Danfoss A/S. All rights reserved.



**Figure 2 – Operating Envelope, High SST: TGS510**

### Action Required

Please reference the corrected Fahrenheit scale of **41°F to 158°F** when reviewing the TTS650 and TGS510 High SST Operating Envelopes.

This update has been incorporated into **M-AP-001-EN Applications and Installation Manual, Revision U.1**.

### Need Assistance

DTC Applications is available to support our OEM customers. Contact DTC Applications ([dtcapplications@Danfoss.com](mailto:dtcapplications@Danfoss.com)) directly or your local Key Account Manager with any questions.

Classified as Business

**Danfoss LLC • 1769 E Paul Dirac Drive • Tallahassee, FL 32310 USA • [turbocor.ps.na@danfoss.com](mailto:turbocor.ps.na@danfoss.com) • <http://turbocor.danfoss.com> • Phone +1 850 504 4800**

Danfoss can accept no responsibility for possible errors in catalogues, brochures and other printed material. Danfoss reserves the right to alter its products without notice. This also applies to products already on order provided that such alterations can be made without subsequent changes being necessary in specifications already agreed. All trademarks in this material are property of the respective companies. Danfoss and the Danfoss logotype are trademarks of Danfoss A/S. All rights reserved.