

**Bulletin | Danfoss Turbocor Compressors** 

# **Customer Notification**

**B-CN-321-EN REV A** 


June 30, 2023

SUBJECT: PWM Connectors

## **Purpose**

The purpose of this bulletin is to inform our customers that we have changed the location of the heat shrink tubing on the two (2) PWM connectors. The heat shrink tubing has been pushed back by 25mm on both cables (4 and 6 pin). This change will improve the strain relief on the PWM cables, thus improving the cable reliability.

The table below illustrates the new location of the heat shrink tubing.



The spare part kits will now include the updated heat shrink configuration. The spare part kit part numbers will not change.

### Summary

We have updated the heat shrink tubing configuration on the PWM connectors to improve the strain relief on the cable.

The spare part kit part numbers remain unchanged. Please reference the spare part kit numbers in the table below. Any compressors or kits shipped as of the date of this bulletin release will include the updated heat shrink configuration.

Part Number	Major Revision	Details
100022	-N, -P, -A, -C, -D, -E	Not impacted by this change
100372	-F, -G, -H	Heat shrink tubing modification

### **Action Required**

No action is required.

#### **Need Assistance**

For more information, please contact your Key Account Manager or our Product Support group at <a href="mailto:turbocor.ps.na@danfoss.com">turbocor.ps.na@danfoss.com</a>.