

Bulletin | Danfoss Turbocor Compressors

Customer Notification

B-CN-056-EN REV A

1/10/2017

SUBJECT: Discontinuation of TT500 Model Compressors**Purpose**

The purpose of this document is to notify customers that effective March 31, 2017 Danfoss Turbocor will no longer be providing new TT500 compressors.

The TT700 compressor which was released in late 2016 covers the same operating range of the TT500 or more in the case of 400V applications. Performance of the TT700 is equivalent to the performance of the TT500.

Affected Components

This only affects new TT500 compressors. Refurbished TT500 compressors will continue to be available depending on core availability. Factory repairs of TT500 compressors will also continue to be supported.

There will be no change in the support of spare parts for TT500 compressors and these will continue to be available as listed in the spare parts manual.

New TT700 compressors are compatible in place of new TT500 compressors. Due to software configuration differences, there may be some chiller controller compatibility differences which have to be considered. TT700 compressors are available only with version 4.0 BMCC firmware and later.

Action Required

Please plan accordingly for the phase-out of the TT500s. Orders for TT500 extending beyond March 31, 2017 will need to be corrected to reflect the part numbers for TT700.

For any specific conversion issues, please contact your Key Account manager or Danfoss Turbocor product support at product.support@danfoss.com.